



330 N. Ross St. Beaveron, Michigan 48612, USA
Ph: 989.435.7741 TF: 877.702.4142
sales@brown-machine.com

SERVICE BULLETIN
iALERT!

**Attention Brown Thermoforming Customers:
Yaskawa has announced that after years
of success the MP940 Single Axis
Motion Controller will be discontinued
effective August 27, 2010.**

Key Information:

- New units are available through Brown while quantities are available from Yaskawa. Yaskawa has announced a projected list price increase of up to 25% after August 27, 2010.
- Repair exchange support will be available from Brown and Yaskawa through August 2017, depending on component availability to support this service. The purchase of a refurbished unit will require returning the existing unit.
- All MP940 Motion Controllers currently covered under Brown and/or Yaskawa warranties will be honored by Brown and/or Yaskawa.
- A direct replacement is not available at this time from Yaskawa; however an MP2300 Multi Axis Motion Controller can be retrofitted.

To avoid any production interruptions we highly recommend that you consider the following:

1. Awareness within your organization of the discontinued availability by Yaskawa of the MP940 Motion Controller and available alternative actions.
2. Purchase of a spare MP940 Motion Controller: reference Brown #540-35190.
3. Contact our Kit Sales Department to schedule and upgrade to an MP2300 Motion Controller.

